



U.S. Department
of Transportation
**Federal Aviation
Administration**

Aviation Safety

Los Angeles Flight Standards District Office
777 S. Aviation Boulevard, Suite 150
El Segundo, CA 90245
Phone: (424) 405-7870, Facsimile (424) 405-7866

December 4, 2023

VIA E-MAIL ONLY

Mr. Oscar Hernandez
FAA Accountable Manager
Leach International Corporation
6900 Orangethorpe Avenue
Buena Park, CA. 90620
Oscar.Hernandez@leachcorp.com

Dear Mr., Hernandez,

This letter is to inform you that as of December 4, 2023, the Leach International Corporation Repair Station Capabilities List, revision N, dated December 4, 2023, has been reviewed and accepted as submitted.

Please place a copy of this letter in front of your manual.

If you have any questions/concerns, please contact me at the number listed above.

Regards,

CHARLES E Digitally signed by
JOHNSON CHARLES E JOHNSON
Date: 2023.12.04
12:07:14 -08'00'

Charles E. Johnson
Principal Maintenance Inspector

512 Repair Station Document
**Capability List For FAA Approved Repair Station
 NO.FJ3D503L**

**Leach International
 Corporation**

Signatures on file.

To prevent the unintended use of obsolete documented information, this document should not be used unless the user has verified this document is current. Current documents are available on the QMS SharePoint database.

| | | | |
|-------------------------------|--------------|---|----------------------|
| DRAWN | P. Sharma | Leach International Corporation | |
| RS Supervisor | P.Sharma | | |
| FAA Accountable Manager | O. Hernandez | | |
| Director, Quality | O. Hernandez | | |
| | | DOCUMENT TITLE: CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| | | DOC NO. 512-0006-001-000 | REV. N |
| | | Release Date: 12/04/2023 | SHEET 1 OF 16 |

DOCUMENT CHANGE HISTORY

| REV | Page(s) Affected | DCN/Description of Change | Date | Initiator |
|-----|------------------|--|------------|-----------|
| N/C | | Document Controlled By Quality Assurance | 1-30-04 | JG |
| A | | Revised to add New Model Numbers per 512-0006-000 | 8-23-06 | JG |
| B | | Revised to remove Model Numbers never repaired | 9-25-06 | JG |
| C | | Revised to remove four Model Numbers | 9-22-07 | JG |
| D | | Revised to add New Model Numbers per 512-0023-000 | 04-28-09 | MS |
| E | | REVISED TO DCN 0234 | 02-10-11 | JG |
| F | | DCN 0406 | 1-23-14 | ML |
| G | | DCN 0438 | 3-24-14 | ML |
| H | | DCN 0607 | 7/17/15 | PSharma |
| J | | DCN 0837 | 4/13/16 | PSharma |
| K | All | DCN 2016-190 Name change from Leach International North America to Leach International Corporation | 12/15/2016 | PSharma |
| | | Update format to QAF-211 Rev C template | | |
| L | All | DCN 2017-120 Update to current format QAF 211 Rev D | 4/20/17 | MLangley |
| | Pg. 8 | Add ZE-X9YN-016 | 4/20/17 | PSharma |
| | Pg. 13 | Add P800-A154-E001 | 4/20/17 | PSharma |
| M | Pg. 13 & 15 | DCN 2021-057 Add ECU-111-001 & FE1561-03 | 7/8/2021 | P.Sharma |
| N | Pg. 13 | DCN 2023-052 Added EPM-112-3 & -4 | 12/4/2023 | P. Sharma |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

NOTE: Add rows as necessary

| | |
|---|----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 2 OF 16 |

TABLE OF CONTENTS

Cover Sheet.....1

Document Change History.....2

Table of Contents.....3

1. PURPOSE4

2. APPLICABILITY4

3. SCOPE4

4. RECORD RETENTION4

5. REFERENCE DOCUMENTS4

6. DEFINITIONS4

7. ROLES & RESPONSIBILITIES5

8. PROCEDURE5-16

NOTE: When adding to the table of contents, enter the section number, the title, press the tab key and then the page number of the section

| | |
|---|----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 3 OF 16 |

1. PURPOSE

This Capability List has been prepared in accordance with the current Code of Federal Regulation (CFR) part 145.215 and the policies of Leach International Corporation and set forth the requirements and policies of this Repair Station, which are to be observed by all repair station employees.

2. APPLICABILITY

This Capability List applies to all repair station employees located at Leach International Corporation which is physically located at 6900 Orangethorpe Avenue in Buena Park, CA 90620. The mailing address is 6900 Orangethorpe Ave, Buena Park CA 90620. The telephone number is 714 739-0770.

3. SCOPE

Capability List includes all the articles on which FJ3D503L Repair Station can perform maintenance, preventive maintenance or alterations. This repair station will not repair or alter any item for which it is not rated, and will not repair or alter any article for which it is rated if it requires technical data, equipment, materials, facilities, or trained personnel that are not available.

4. RECORD RETENTION

Records established to provide evidence of conformity to requirements and of the effective operation of the quality management system shall be controlled in accordance to QAP 2.3 Data Retention/Data Control.

5. REFERENCE DOCUMENTS

| <u>Document Number</u> | <u>Document Name</u> |
|------------------------|---|
| 512-0000-000-000 | Business Management System Manual |
| 512-0006-000-000 | Repair Station & Quality Control Manual |
| QAP 2.3 | Data Retention/Data Control |
| QAP 9.0 | Trade Compliance Program |
| MRL | Master Records List |

6. DEFINITIONS

| Term | Definition |
|-------------|---|
| Red Flags | <ul style="list-style-type: none"> Any unusual circumstances that indicate a party to transaction is prohibited end-user or Defense Technology / Defense Articles are destined to a prohibited end-use location. Special care should be taken to prevent transactions with entities involved in proliferation of weapons of mass destruction |
| CFR | <ul style="list-style-type: none"> Code of Federal Regulations |

| | |
|---|----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 4 OF 16 |

7. ROLES & RESPONSIBILITIES

| Role | Responsibilities |
|-------------------|---|
| Company Employees | <ul style="list-style-type: none">Maintain full compliance with all applicable laws and regulations that protect and support the national security, foreign policy, and commerce of the United States and other countries in which Company operates |

NOTE: Add rows as necessary

8. PROCEDURE

See the Capability List

| | |
|---|-----------------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 5 OF 16 |

| BALANCED ARMATURE | |
|--------------------------|-------------|
| 9220-4186 | 9324-10128 |
| 9220-4948 | 9324-10314 |
| 9220-8023 | 9324-10315 |
| 9223-8721 | 9324-10559 |
| 9224-3823 | 9324-10627 |
| 9224-4076 | 9324-7424 |
| 9224-4091 | 9324-8213 |
| 9224-4091-CON | 9324-8214 |
| 9224-4487 | 9324-8266 |
| 9224-4488 | 9324-8663 |
| 9224-5532 | 9324-8873 |
| 9224-5534 | 9324-9261 |
| 9224-8834 | 9324-9337 |
| 9226-3592 | 9325-10461 |
| 9226-4187 | 9325-8377 |
| 9226-4277 | 9325-8390 |
| 9226-4429 | 9325-8398 |
| 9226-5046 | 9325-8723 |
| 9226-6601 | 9325-8994 |
| 9227-10127 | 9326-4386 |
| 9227-10410 | 9330-4026 |
| 9227-10635 | 9339-10223 |
| 9227-4084 | 9339-10274 |
| 9227-4473 | 9339G-10683 |
| 9227-4517 | 9346-10129 |
| 9227-8982 | 9346-8233 |
| 9229-4457 | 9346-8572 |
| 9229-4459 | 9346-8862 |
| 9229-4461 | 9346-8946 |
| 9229-6735 | 9420- |
| 9235-4842 | 9524-10214 |
| 9237-4845 | 9524-6506 |
| 9237-5567 | 9524-6507 |
| 9274-10291 | 9524-6508 |
| 9274-3642 | 9524-8208 |
| 9274-3643 | 9524G-10674 |
| 9274-6205 | 9837-10472 |
| 9274-6667 | 9838-10458 |
| 9274-6686 | 9838-10460 |
| 9274-7813 | 9838-10463 |
| 9274-8681 | 9838-10464 |
| 9274-8730 | 9838-10555 |
| 9274-9016 | 9838-10564 |

| POWER DISTRIBUTION ASSEMBLY |
|------------------------------------|
| CSA-101 |
| PDA-105 |
| PDA-111 |
| PDA-137 |
| PDA-138 |
| PDA-139 |
| PDA-145 |

| GROUND FAULT INTERRUPTER |
|---------------------------------|
| 9130G-10677 |
| 9324G-10675 |
| 9324G-10676 |
| HDG-X2N-001 |
| HTDG-X7N-001 |
| KCG-X4L-001 |
| KDAG-X4F-001 |
| KDG-X4L-001 |
| HDGE-X3F-001 |

| | |
|---|----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 6 OF 16 |

| POWER & CONTROL CONTACTORS | | | |
|---------------------------------------|------------|--------------|--------------|
| 9123-1Z-C7C4-002 | 9132-8655 | A-A4A-013 | C400-9363 |
| 9123-8056 | 9132-8656 | A-A4N | C400-9436 |
| 9123-8071 | 9133-8657 | A-A4N-103 | C400-A1N-223 |
| 9123-8072 | 9133-8678 | AH-C6A-020 | C400-A2N |
| 9123-8865 | 9204-6946 | AH-C9N-033 | C400-B3N |
| 9123-C7C4-002 | 9205-4584 | AH-CXA-016 | C400-B3N-001 |
| 9123-C7D3-002 | 9205-7802 | AHJS-CXA-040 | C600-9374-A |
| 9124-10280 | 9207 | AHS-CXA-034 | C600-A11N |
| 9124-10400 | 9207-10296 | AJ-A4N-176 | C600-A3A |
| 9124-1Z-C7C4-002 | 9207-10339 | AJ-A7N-210 | C600-A3N-001 |
| 9124-1Z-C7D3-002 | 9207-10340 | AJ-A8N | C600-A4N |
| 9124-8063 | 9207-3731 | AJ-B4N-180 | C600-A9N-001 |
| 9124-8073 | 9207-4399 | AJ-B5N | C750-B2F |
| 9124-8075 | 9207-4521 | AJ-B7N-175 | C800-9395 |
| 9124-8075A | 9207-5340 | AJ-R1N-220 | C800-B10N |
| 9124-9252 | 9207-7254 | AJ-R5N-221 | CED-1065 |
| 9124-9283 | 9207-7803 | AJ-R7N-222 | CED-1066 |
| 9124-9290 | 9207-8053 | AJ-T17N-217 | C-G1A-010 |
| 9124-9318 | 9207-8339 | AJS-A4N-012 | CSH-247-1 |
| 9124-9417 | 9207-9238 | | CSH-267 |
| 9124-9426 | 9207-9274 | | |
| 9124-9446 | 9207-9340 | | |
| 9124-10398 | 9213-10124 | | |
| 9124-C7C4-002 | 9213-3966 | | |
| 9124-C7D3-002 | 9840-10558 | | |
| 9125-2ZC7C4-001 | 9840-10582 | | |
| 9130-8463 | 9901-8768 | | |
| 9130-8504 | | | |
| 9131-10415 | | | |
| 9131-8388 | | | |
| 9131-8505 | | | |
| 9131-8506 | | | |

| | |
|---|----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 7 OF 16 |

| POWER & CONTROL CONTACTORS | | | | |
|----------------------------|--------------|------------|-------------|-------------|
| H-A10N | HC-C3N | L-B3N-014 | W-A1N | Z-A1A-052 |
| H-A10N-109 | HC-C9N-010 | L-B79-013 | WC-A3F-018 | Z-A2A-080 |
| H-A1A-002 | HCD-A1A-011 | L-B7N-013 | WC-A3F-027 | Z-A3YN-079 |
| H-A1F-002 | HC-T3A-021 | L-B9N-013 | WC-A4F-020 | Z-A4N |
| H-A1N | HCTD-A1N-030 | LC-A2N-012 | WC-A9N-019 | Z-A6N |
| H-A1N-051 | HD-A1F-014 | LC-B9N-014 | WC-A9N-025 | Z-A9A-038 |
| H-A1N-059 | HD-A3F-011 | M600-9336 | WE-X2YN-014 | Z-A9N-042 |
| H-A2A-002 | HD-A9A-021 | Z-X9N-049 | WE-X9YN-013 | Z-B7N-043 |
| H-A2A-021 | HD-X9F-011 | | WL-A10N | Z-B7N-059 |
| H-A2A-043 | HD-X9N-025 | | WL-R9N-016 | Z-B7YN |
| H-A2A-119 | HL-A1A-002 | | W-R1N-033 | Z-B9N-062 |
| H-A2A-126 | HL-C3N-030 | | W-R10N-036 | ZC-A2N |
| H-A2F | HLT-A1A | | | ZC-A2N-020 |
| H-A2F-002 | HLT-A1A-002 | | | ZC-A9X-036 |
| H-A2N | H-R4N-143 | | | ZC-B3N |
| H-A3A-002 | H-R10N | | | ZC-B3N-018 |
| H-A3F | H-R10N-144 | | | ZC-B3N-031 |
| H-A3F-002 | HT-A10N | | | ZC-B4N-021 |
| H-A3N | HT-A4F | | | ZC-B5F-040 |
| H-A3N-117 | HT-A4F-002 | | | ZC-B5N-039 |
| H-A4A-002 | HT-A4N | | | ZC-X9N-044 |
| H-A4A-039 | HT-A5A-002 | | | ZCD-B9A-015 |
| H-A4F-002 | HT-C7F | | | ZCD-B9N-012 |
| H-A4N | HT-C7F-072 | | | ZC-B9N-034 |
| H-A4N-120 | HT-C7N | | | ZCD-A1A-047 |
| H-A5A-002 | HT-C7N-060 | | | ZCD-A2X-021 |
| H-A5N | HT-C7N-071 | | | ZCD-B9A-012 |
| H-A6N | HT-C7N-073 | | | ZCD-B9A-022 |
| H-A6N-054 | HTD-C7N-012 | | | ZCD-B9A-023 |
| H-A6N-157 | H-X2A-011 | | | ZC-T5N |
| H-A9A-004 | H-X9A-101 | | | ZD-A5A-045 |
| H-A9A-040 | HC-A1N-024 | | | ZD-B4A-011 |
| H-A9A-042 | HC-A1N | | | ZD-B4A-017 |
| H-A9A-048 | HC-A1N-022 | | | ZD-B9A-016 |
| H-A9N-078 | | | | ZE-X9YN-016 |
| H-A9N-093 | | | | ZG-A1N |
| H-C7N | | | | ZG-K7YN-020 |
| H-C9N-011 | | | | ZJ-A3N-016 |
| HC-A1A | | | | ZJC-B9N-015 |
| HC-A1A-002 | | | | ZJ-T10N-031 |
| HC-A1A-017 | | | | Z-R2N-086 |
| HC-A1A-020 | | | | Z-R4N-087 |
| HC-A1F-014 | | | | Z-T8N-063 |
| HC-A1F-029 | | | | ZL-B7N |

| | |
|---|-----------------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 8 OF 16 |

| SUBMIN RELAYS | | | | |
|---------------|------------|------------|-------------|-------------|
| J-A1A | JC-A1A | J-D1A | JL-A2G-254V | KA-D2F-300L |
| J-A1A-300M | JC-D1A-003 | J-D1A-016 | JL- J2A-081 | KA-D4F |
| J-A2A | JC-D1A-102 | J-D1A-300M | JL-A2A-039 | KA-D4F-033 |
| J-A2B | JC-D1N-103 | J-D1N-300M | JL-A2A-042 | KA-D4F-036 |
| J-A9A-016 | JC-D1N-104 | J-D2A-029 | JL-A9A-009 | KA-D4F-300L |
| JA-D2F-300L | JC-D2A-003 | J-D2A-300M | JL-D1A-023 | KA-D4K-300L |
| JA-D2K-300L | JC-D4A-003 | J-D2L-045 | JL-D2A-108 | KA-D9E-011 |
| JA-D4F-022 | JC-D4A-102 | J-D2L-138 | JL-D2A-116 | KA-D9F-005 |
| JA-D4F-034 | JC-D4N-103 | J-D1A-300M | JL-D2A-163 | KA-D9F-010 |
| JA-D4F-300L | JC-D2A-003 | J-D1N-300M | JL-D2A-300L | KA-J2K |
| JA-D4K-300L | JC-D4A-003 | J-D2L-149 | JL-D2N-300L | KA-J2K-300L |
| JA-D9E-006 | JC-D4A-102 | J-D2N | JL-D4A | KA-X4F-007 |
| JA-D9E-009 | JC-D4N-103 | J-D2N-300M | JL-D4A-300L | KA-X9E-004 |
| JA-D9E-011 | JC-D2A-003 | J-D4A-017 | JL-D4N | K-B4N-300M |
| JA-D9F-007 | JC-D4A-003 | J-D4A-019 | JL-D4N-300L | |
| JA-D9F-008 | JC-D4N-104 | J-D4A-063 | JL-D9L-011 | |
| JA-D9F-010 | JC-J1A | J-D4A-300M | JL-J2A | |
| JA-D9L-016 | JC-J1N-103 | J-D4B-056 | JL-J2A-081 | |
| JA-G2K | JC-J2A-102 | J-D4L-025 | JL-J2B | |
| JA-J2F-300L | JC-J7N-012 | J-D4L-031 | JL-J2B-210 | |
| JA-J2K-300L | JC-J9N-009 | J-D4L-050 | JL-J2B-254V | |
| JA-W4F-005 | JC-X7A-012 | J-D4L-115 | JL-J2C | |
| | JCA-D2E | J-D4N | JL-J7A | |
| | JCL-D4N | J-D4N-059 | JL-J7A-017 | |
| | | J-D4N-300M | J-W4N-005 | |
| | | J-D4N-304M | JL-X9AP-014 | |
| | | J-D9B-013 | | |
| | | J-D9L-006 | | |
| | | J-G2A | | |
| | | J-G2A-019 | | |
| | | J-G2F-009 | | |
| | | J-J1N-300M | | |
| | | J-J2A-028 | | |
| | | J-J2A-300M | | |
| | | J-J2N-300M | | |
| | | J-J7A-300M | | |
| | | J-J9A-017 | | |

| | |
|---|-----------------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 9 OF 16 |

| SUBMIN RELAYS | | | |
|---------------|--------------|-------------|-------------|
| KC-A1A | KCL-A1V-020 | K-A1N | KDL-D1A-012 |
| KC-A1N | KCL-D1A | K-A1N-300M | KDL-D2A-002 |
| KC-A1N-011 | KCL-D2A-002 | K-D1A-300M | K-G1A |
| KC-A4A | KCL-D2A-064 | K-D1B-300M | K-G2A |
| KC-D1A-300L | KCL-D2A-073 | K-D1N | K-G2A-014 |
| KC-D1N-300L | KCL-D2A-100 | K-D1N-300M | |
| KC-D2A-003 | KCL-D2A-110 | K-D2A-028 | |
| KC-D2A-052 | KCL-D2A-125 | K-D2A-109 | |
| KC-D4A-016 | KCL-D2A-254V | K-D2A-300M | |
| KC-D4L-013 | KCL-D4A-002 | K-D2N-300M | |
| KC-D4N-103 | KCL-D4N | K-D4A-017 | |
| KCA-E4E | KCL-J2A-023 | K-D4A-019 | |
| KCA-E4F | KCL-J2A-031 | K-D4A-025 | |
| KCA-J2F | KCL-J2A-036 | K-D4B-066 | |
| KCA-W9F-008 | KCL-J2A-047 | K-D4L-030 | |
| KCA-X9F-006 | KCL-J2A-254V | K-D4L-036 | |
| KC-D2A-300L | KCL-X1A-010 | K-D4L-050 | |
| KC-D2L-059 | KCL-X1A-011 | K-D4L-113 | |
| KC-D2N-300L | K-A1A | K-D4N | |
| KC-D4A | K-A1A-300M | K-D4N-068 | |
| KC-D4A-003 | | K-D4N-300L | |
| KC-D4A-300L | | K-D4N-300M | |
| KC-D4N | | K-D4N-304M | |
| KC-D4N-021 | | K-D4V | |
| KC-D4N-033 | | K-D9L-012 | |
| KC-D4N-104 | | K-X1N-008 | |
| KC-D4N-300L | | KDA-E4E | |
| KC-J2A | | KDA-E4F | |
| KC-J2A-003 | | KDA-E4F-002 | |
| KC-J2A-102 | | KD-A1N | |
| KC-J2A-300L | | KD-A1N-103 | |
| KC-J2N-103 | | KD-D1N-103 | |
| KC-J2N-300L | | KD-D1N-104 | |
| KCL-A1A-014 | | KD-D2A-002 | |
| | | KD-D2A-018 | |
| | | KD-D2N-103 | |
| | | KD-D4A | |
| | | KD-D4A-002 | |
| | | KD-D4N | |
| | | KD-D4N-103 | |
| | | KD-J1A-102 | |
| | | KD-J2A-002 | |
| | | KD-J2N-103 | |
| | | | |

| | |
|---|------------------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 10 OF 16 |

| SUBMIN RELAYS | | | |
|---------------|-------------|-------------|------------|
| K-J1A | KM-J5N | X-A1A | XL-D4N |
| K-J2A | KM-U5A | X-A1B | XL-D4N-009 |
| K-J2A-300M | KM-U5AL | X-A1B-300M | XL-J2A |
| K-J2N-300M | KM-U5N | X-A1A-036 | XL-J2A-003 |
| KL-A9A-012 | KM-U5NL-011 | X-A1A-045 | XL-J7A-024 |
| KL-D1B-025 | KM-U5NL-012 | X-A1N-035 | X-X9N-011 |
| KL-D1C | KM-U5NL-014 | X-A1N-300M | |
| KL-D2A-071 | KMN-D9N-011 | X-A4N-300M | |
| KL-D2A-085 | KUL-X9A-004 | X-A9A-014 | |
| KL-D2A-300L | K-W4N-004 | X-A9A-020 | |
| KL-D2C | KX-D5N | XA-E9K-011 | |
| KL-D4A-011 | KXL-A9A-011 | XC-D1A-009 | |
| KL-D4A-037 | KXL-A9A-015 | XC-J7A | |
| KL-D4L-025 | KXL-X9A-011 | XC-J7A-012 | |
| KL-D4L-029 | KXL-X9A-012 | X-D1A-300M | |
| KL-D4N | KXL-X9A-022 | X-D1N-015 | |
| KL-D4N-300L | | X-D1N-018GD | |
| KL-G2C | | X-D1N-019 | |
| KL-X4A-011 | | X-D1N-300M | |
| | | X-D2N-019 | |
| | | X-D2N-300M | |
| | | X-D4A-300M | |
| | | X-D4L-015 | |
| | | X-D4N | |
| | | X-D4N-023 | |
| | | X-D4N-300M | |
| | | X-E4N-023 | |
| | | X-E4N-024 | |
| | | X-E4N-300M | |
| | | X-G2N | |
| | | X-J2A | |
| | | X-J2N | |
| | | X-J2N-300M | |
| | | X-J7A-027 | |
| | | X-J7A-300M | |
| | | X-J7N-012 | |
| | | X-J7N-013 | |
| | | XL-A1A | |
| | | XL-A1A-009 | |
| | | XL-A9A-015 | |
| | | XL-A9A-016 | |
| | | XL-D1A-003 | |
| | | XL-D1A-017 | |
| | | XL-D2A-003 | |
| | | XL-D2N | |
| | | XL-D4A | |

| | |
|---|-----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 11 OF 16 |

| SUBMIN RELAYS | |
|----------------------|------------|
| Y-A1A-300M | Y-D1N-300M |
| Y-A1N | Y-D2A-019 |
| YA-D4F | Y-D2N-300M |
| YC-A1N | Y-D2R-300M |
| YC-A1N-300M | Y-D4N |
| YC-A4N-300M | Y-D4N-023 |
| YC-D1A-300M | Y-D4N-300M |
| YC-D1N-300M | Y-E4C-012 |
| YC-D2N-300M | Y-E4N-023 |
| YC-D4A | Y-E4N-024 |
| YC-D4A-300M | Y-E4N-300M |
| YC-D4N | Y-J2A-016 |
| YC-D4N-300M | Y-J2A-300M |
| YC-E4N-300M | Y-J2N |
| YC-J2A-300M | Y-J2N-015 |
| YC-J2N-300M | Y-J2N-300M |
| YCL-A1A-003 | YL-A1A-023 |
| YCL-A1A-016 | YL-A1A-026 |
| YCL-A1B-013 | YL-D1A-003 |
| YCL-A1B-017 | YL-D1A-013 |
| YCL-D1A-003 | YL-D4A-003 |
| YCL-D1A-016 | YL-D4N |
| YCL-D1A-254V | YL-J2N |
| YCL-D1C | |
| YCL-D4A-003 | |
| YCL-X1A-012 | |

| | |
|---|-----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 12 OF 16 |

| RELAYS, ELECTRONIC UNITS, TIME DELAY AND TIME DELAY HYBRIDS | | | | |
|--|------------------|----------------|---------------|--------------|
| ECU-101 | P111-B253-S001 | TD-640-30S-1 | TD-1654-3001 | TD-1982-3001 |
| ECU-103 | P111-B253-S301 | TD-974 | | TD-1982-4001 |
| ECU-104 | P140-A402-A101 | TD-1023 | TD-1700 | TD-1982-5001 |
| ECU-106 | P140-A402-A301 | TD-1030 | TD-1702-1002 | TD-1982-7000 |
| ECU-107-1 | P150-A153-A031 | TD-1032-B | TD-1715-1002 | TD-1982-7500 |
| ECU-108 | P150-A253-A031 | TD-1040 | TD-1718-2001 | TD-1982-7501 |
| EP-149 | P150-A253-A331 | TD-1047 | TD-1721-3500 | TD-1989-2202 |
| EP-231 | P150-A702-A332 | TD-1047-10S | TD-1738-1002 | TD-1990-3001 |
| EP-361 | P152-A202-A051 | TD-1047-180S | TD-1745 | TD-1996-1202 |
| EP-375 | P170-A153-A001 | TD-1047-550M | TD-1762-1002 | TD-2000-5000 |
| EP-383 | P170-A202-A001 | TD-1068 | TD-1781-6002 | TD-2001-1502 |
| EP-393 | P170-A702-A001 | TD-1069 | TD-1782-2001 | TD-2004-1002 |
| EP-395 | P600-A803-E011 | TD-1142 | TD-1784-1001 | TD-2027-4502 |
| EP-402 | P600-A803-E013 | TD-1164 | TD-1796-3002 | TD-2028-2001 |
| EP-410 | P600-A803-E015 | TD-1192 | TD-1815-5001 | TD-2040-2501 |
| ECU-111-001 | P700-A154-E002 | TD-1195 | TD-1836-5001 | TD-2042-6002 |
| EP-449-1501 | P800-A154-E001 | TD-1197 | TD-1854-2500 | TD-635-60S |
| EP-449-3001 | R101-AXE-5001-FC | TD-1239 | TD-1862-7500 | TD-640-10S |
| EP-449-4001 | R101-BNJ-2002-BA | TD-1263 | TD-1862-7500A | TD-640-15S |
| EP-449-5001 | R102-DNE-3003-HB | TD-1273 | TD-1868-1002 | TD-640-2S |
| EPH-403 | | TD-1324-00 | TD-1868-2002 | TD-640-300M |
| EPH-404 | | TD-1340-00 | TD-1904-5001 | TD-640-30S |
| EPH-423 | | TD-1383-00 | TD-1951-3003 | TD-640-3S |
| EPH-345-1 | | TD-1412-5000A | TD-1955-5000 | TD-640-60S |
| EPH-438 | | TD-1434-00 | TD-1956-2000 | TD-770 |
| EPH-443 | | TD-1684-5001 | TD-1958-5000 | TD-823 |
| EPH-473 | | TD-1436-5000W | TD-1959-6002 | TD-870-1.4S |
| EPH-490 | | TD-1436-5002AW | TD-1971-7500 | TD-870-2.1S |
| EPH-492-1 | | TD-1439-01 | TD-1972-1251 | TD-929 |
| EPH-494 | | TD-1440-00 | TD-1975-3003 | TD-947 |
| EPM-112 | | TD-1452-00 | TD-1982-1000 | TD-948 |
| EPM-112-1 | | TD-1468-5000 | TD-1982-1002 | TD-950 |
| EPM-112-2 | | TD-1482-7500 | TD-1982-1502 | TD-975 |
| EPM-112-3 | | TD-1507-3002 | TD-1982-2001 | |
| EPM-112-4 | | TD-1508-3001 | TD-1982-2500 | |
| | | TD-1542-2002 | TD-1982-3000 | |
| | | TD-1549-1001 | | |
| | | TD-1553-1202 | | |
| | | TD-1626-9002 | | |
| | | TD-1644-2001 | | |

Leach International Corporation

**CAPABILITY LIST FOR FAA APPROVED
REPAIR STATION NO. FJ3D503L**

| | |
|------------------------------------|-----------------------|
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 13 OF 16 |

| RELAYS, ELECTRONIC UNITS, TIME DELAY AND TIME DELAY HYBRIDS | | | |
|--|---------------|----------------|---------------|
| TDH-1610-XXXXW | TDH-1994-4502 | TDH-8002-XXXX | V110-J-003-AC |
| TDH-1685-6002 | TDH-1999-5001 | TDH-8003-XXXX | V110-J-020-AC |
| TDH-1729-2500 | TDH-2006-XXXX | TDH-8050-XXXXP | V110-J-023-AC |
| TDH-1743-1002 | TDH-2012-5001 | TDH-8051-XXXXS | V110-J-024-AB |
| TDH-1798-XXXX | TDH-2021-2001 | TDH-8060-XXXXP | V110-J-032-AC |
| TDH-1852-XXXX | TDH-2029-8001 | TDH-8061-XXXXS | V110-K-018-AA |
| TDH-1853-XXXX | TDH-2030-XXXX | TDH-8070-XXXXP | V110-K-024-AC |
| TDH-1918-XXXX | TDH-2031-XXXX | TDH-8071-XXXXS | V210-D-090-BC |
| TDH-1925-XXXX | TDH-6050-XXXX | TDH-8080-XXXXP | V210-K-090-BB |
| TDH-1960-8001 | TDH-6060-XXXX | TDH-8081-XXXXS | V610-BJCC-90 |
| TDH-1961-1002 | TDH-6061-XXXX | TDH-8103-1001 | V610-HJFF-108 |
| TDH-1962-5001 | TDH-6070-XXXX | TDH-8116-XXXX | VS-129 |
| TDH-1964-4001 | TDH-6071-XXXX | TDH-8117-5000 | VS-215-1 |
| TDH-1965-6001 | TDH-6103-XXXX | TDH-8119-XXXX | VS-223-1 |
| TDH-1970-6002 | TDH-6108-XXXX | TDH-8120-XXXX | VS-233-1 |
| | TDH-6110-8001 | TDH-8124-3403 | VS400-2063 |
| | TDH-7050-XXXX | TDH-8127-XXXX | VS-403 |
| | TDH-7051-XXXX | TDH-8140-XXXX | VS-454 |
| | TDH-7060-XXXX | TDH-8150-XXXX | VS-455-1 |
| | TDH-7061-XXXX | TDH-8186-XXXX | VS-456-1 |
| | TDH-7070-XXXX | TDH-8189-XXXX | VS-527 |
| | TDH-7071-XXXX | | VS-534 |
| | TDH-7101-XXXX | | VS-539 |
| | TDH-7111-0500 | | VS-568-1 |
| | TDH-7119-7500 | | VS-576 |
| | TDH-7120-XXXX | | VS-584B |
| | TDH-7122-5001 | | VS-601 |
| | TDH-7126-0500 | | VS-621 |
| | | | VS-629 |
| | | | VS-630 |
| | | | VS-633 |
| | | | VS-635 |
| | | | VS-636 |
| | | | VS-643 |
| | | | VSH-488 |
| | | | 9269-10117 |
| | | | 9269-10139 |
| | | | 9269-3759 |
| | | | |

| | |
|---|-----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 14 OF 16 |

| LEACH INTERNATIONAL EUROPE (LIE) | | | | | |
|----------------------------------|--------------------------------|-------------|-----------------|------------|-----------|
| PANELS | MECHANICAL/ELECTRONIC ASSEMBLY | | OVERHEAD PANELS | PC BOARDS | |
| 90020 | FE940 | FE892 | FE1248-5 | 00 2319 00 | FE1063 |
| 90020-2 | FE1137 | FE892-01 | FE1248-5A | 00 2320 00 | FE1066 |
| 90050-3 | FE1524-03 | FE892-02 | FE1248-6 | 00 2352 00 | FE1089 |
| 90050-4 | FE1524-04 | FE897 | FE1248-6A | 00 2353 00 | FE1089-1 |
| 90200-1 | FE1525-03 | FE1608L-516 | FE1248-7 | 00 2368 00 | FE1121 |
| 90200-2 | FE1525-04 | FE1608R-520 | FE1248-7A | 00 2369 02 | FE1141 |
| 90300-4 | FE1549R-01 | | FE1331-5 | 00 2569 00 | FE1145 |
| 90310 | FE1549R-02 | | FE1331-5A | 00 2569 01 | FE1210 |
| 90350-1 | FE1561 | | FE1385S3-5 | 00 2570 00 | FE1243 |
| 92417 | FE1561-01 | | FE1385S3-5A | 00 2570 01 | FE1243-1 |
| 92418 | FE1561-02 | | FE1385S3-5B | FE422-01 | FE1243-2 |
| | FE1561-03 | | FE1385S3-5AB | FE457 | FE1263 |
| 00 2265 00 | FE1607-512 | | FE1385S3-6 | FE460 | FE1278 |
| 00 2358 01 | FE1609-520 | | FE1385S3-6A | FE463 | FE1280 |
| 00 3225 00 | FE1610L-524 | | FE1385S3-6B | FE466 | FE1482-3 |
| FE1144 | FE1610R-518 | | FE1385S3-6AB | FE549 | FE1509-01 |
| FE1328 | FE1611-520 | | FE1385S3-8 | FE695 | FE1509-02 |
| FE1401 | FE1611-522 | | FE1385S3-8A | FE713 | FE1509-03 |
| FE1415 | FE1612-514 | | FE1385S3-8B | FE714 | FE1509-06 |
| FE1422-1 | FE1489 | | FE1385S3-8AB | FE799 | FE1510 |
| FE1526-04 | FE1549L | | FE1533 | FE800 | FE1548-01 |
| FE1526-05 | FE1549L-01 | | FE1533-A | FE854 | FE1663 |
| FE1550-02 | FE1549R | | | FE886 | FE1718 |
| FE1551-02 | FE1549R-03 | | | FE888 | FE1718-01 |
| FE1574-05 | FE1526-03 | | | FE953 | FE1851-1 |
| FE925-1 | | | | FE964 | FE1851-2 |
| FE950-1 | | | FE1002 | 00 4849 81 | |
| | | | FE1002-1 | FE422 | |
| | | | FE1027 | FE424 | |
| | | | FE1038 | FE1056 | |
| | | | | | |
| | | | | | |

| | |
|---|-----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 15 OF 16 |

| SUB-ASSEMBLIES FOR OVERHEAD PANELS (LIE) | | | |
|---|------------|------------|------------|
| 00 3516 00 | 00 3742 81 | 00 3982 02 | 00 4130 46 |
| 00 3714 00 | 00 3742 41 | 00 6185 00 | 00 4130 47 |
| 00 3736 00 | 00 3742 42 | 00 4130 00 | 00 4130 48 |
| 00 3737 00 | 00 3742 43 | 00 4130 01 | 00 4130 49 |
| 00 6186 00 | 00 3742 44 | 00 4130 02 | 00 4130 50 |
| 00 6187 00 | 00 3742 45 | 00 4130 03 | 00 4130 51 |
| 00 6188 00 | 00 3742 46 | 00 4130 04 | 00 4130 52 |
| 00 3742 00 | 00 3742 48 | 00 4130 05 | 00 4130 53 |
| 00 3742 01 | 00 3742 49 | 00 4130 06 | 00 4130 54 |
| 00 3742 02 | 00 3742 50 | 00 4130 07 | 00 4130 55 |
| 00 3742 03 | 00 3742 51 | 00 4130 08 | 00 4130 56 |
| 00 3742 04 | 00 3742 52 | 00 4130 09 | 00 4130 57 |
| 00 3742 05 | 00 3742 53 | 00 4130 10 | 00 4130 58 |
| 00 3742 06 | 00 3742 54 | 00 4130 11 | 00 4130 59 |
| 00 3742 07 | 00 3742 56 | 00 4130 12 | 00 4130 60 |
| 00 3742 08 | 00 3742 57 | 00 4130 13 | 00 4130 61 |
| 00 3742 09 | 00 3742 58 | 00 4130 14 | 00 4130 62 |
| 00 3742 10 | 00 3742 60 | 00 4130 15 | 00 4130 63 |
| 00 3742 11 | 00 3742 61 | 00 4130 16 | 00 4130 64 |
| 00 3742 12 | 00 3742 62 | 00 4130 17 | 00 4130 65 |
| 00 3742 13 | 00 3742 63 | 00 4130 18 | 00 4130 66 |
| 00 3742 14 | 00 3742 64 | 00 4130 19 | 00 4130 67 |
| 00 3742 15 | 00 3742 65 | 00 4130 20 | 00 4130 68 |
| 00 3742 16 | 00 3742 66 | 00 4130 21 | 00 4130 69 |
| 00 3742 17 | 00 3742 67 | 00 4130 22 | 00 4130 70 |
| 00 3742 18 | 00 3742 68 | 00 4130 23 | 00 4130 71 |
| 00 3742 19 | 00 3742 69 | 00 4130 24 | 00 4849 81 |
| 00 3742 20 | 00 3742 70 | 00 4130 25 | |
| 00 3742 21 | 00 3742 71 | 00 4130 26 | |
| 00 3742 22 | 00 3742 72 | 00 4130 27 | |
| 00 3742 23 | 00 3742 73 | 00 4130 28 | |
| 00 3742 24 | 00 3742 74 | 00 4130 29 | |
| 00 3742 25 | 00 3742 75 | 00 4130 30 | |
| 00 3742 26 | 00 3742 76 | 00 4130 31 | |
| 00 3742 27 | 00 3742 77 | 00 4130 32 | |
| 00 3742 28 | 00 3742 78 | 00 4130 33 | |
| 00 3742 29 | 00 3742 79 | 00 4130 34 | |
| 00 3742 30 | 00 3742 80 | 00 4130 35 | |
| 00 3742 31 | 00 3742 82 | 00 4130 36 | |
| 00 3742 32 | 00 3742 83 | 00 4130 37 | |
| 00 3742 33 | 00 3742 84 | 00 4130 38 | |
| 00 3742 34 | 00 3742 86 | 00 4130 39 | |
| 00 3742 35 | 00 3791 00 | 00 4130 40 | |
| 00 3742 36 | 00 3791 01 | 00 4130 41 | |
| 00 3742 37 | 00 3791 02 | 00 4130 42 | |
| 00 3742 38 | 00 3792 00 | 00 4130 43 | |
| 00 3742 39 | 00 3982 00 | 00 4130 44 | |
| 00 3742 40 | 00 3982 01 | 00 4130 45 | |

| | |
|---|-----------------------|
| Leach International Corporation | |
| CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L | |
| DOC NO. 512-0006-001-000 | REV N |
| Release Date: 12/04/2023 | SHEET 16 OF 16 |