



U.S. Department
of Transportation
**Federal Aviation
Administration**

Los Angeles Flight Standards District Office
777 S. Aviation Boulevard, Suite 150
El Segundo, CA 90245
Phone: (424) 405-7870, Facsimile (424) 405-7866

July 8, 2021

VIA E-MAIL ONLY

Mr. Jack Brooks
FAA Accountable Manager – Production Manager
Leach International Corporation
6900 Orangethorpe Avenue
Buena Park, CA. 90620
Jack Brooks Jr (US) <Jack.Brooks@leachcorp.com>

Dear Mr. Brooks,

This letter is to inform you that as of 07/08/2021, the Leach International Corporation Repair Station Capabilities List, revision M, dated 07/08/2021 have been reviewed and accepted as written.

Please place a copy of this letter in front of your manual.

If you have any questions/concerns, please contact me at the number listed above.

Regards

Digitally signed
CHARLES E by CHARLES E
JOHNSON JOHNSON
Date: 2021.07.08
07:08:23 -07'00'

Charles E. Johnson
Principal Maintenance Inspector

512 Repair Station Document
**Capability List For FAA Approved Repair Station
 NO.FJ3D503L**

**Leach International
 Corporation**

Signatures on file.

To prevent the unintended use of obsolete documented information, this document should not be used unless the user has verified this document is current. Current documents are available on the QMS SharePoint database.

DRAWN	P. Sharma	Leach International Corporation	
RS Supervisor	P.Sharma		
FAA Accountable Manager	J. Brooks		
Director, Quality	D. Munro	DOCUMENT TITLE: CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
		DOC NO. 512-0006-001-000	REV. M
		Release Date: 07/08/2021	SHEET 1 OF 16

DOCUMENT CHANGE HISTORY

REV	Page(s) Affected	DCN/Description of Change	Date	Initiator
N/C		Document Controlled By Quality Assurance	1-30-04	JG
A		Revised to add New Model Numbers per 512-0006-000	8-23-06	JG
B		Revised to remove Model Numbers never repaired	9-25-06	JG
C		Revised to remove four Model Numbers	9-22-07	JG
D		Revised to add New Model Numbers per 512-0023-000	04-28-09	MS
E		REVISED TO DCN 0234	02-10-11	JG
F		DCN 0406	1-23-14	ML
G		DCN 0438	3-24-14	ML
H		DCN 0607	7/17/15	PSharma
J		DCN 0837	4/13/16	PSharma
K	All	DCN 2016-190 Name change from Leach International North America to Leach International Corporation	12/15/2016	PSharma
		Update format to QAF-211 Rev C template		
L	All	DCN 2017-120 Update to current format QAF 211 Rev D	4/20/17	MLangley
	Pg. 8	Add ZE-X9YN-016	4/20/17	PSharma
	Pg. 13	Add P800-A154-E001	4/20/17	PSharma
M	Pg. 13 & 15	DCN 2021-057 Add ECU-111-001 & FE1561-03	7/8/2021	P.Sharma

NOTE: Add rows as necessary

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 2 OF 16

TABLE OF CONTENTS

Cover Sheet.....1

Document Change History.....2

Table of Contents.....3

1. PURPOSE4

2. APPLICABILITY.....4

3. SCOPE4

4. RECORD RETENTION.....4

5. REFERENCE DOCUMENTS.....4

6. DEFINITIONS.....4

7. ROLES & RESPONSIBILITIES.....5

8. PROCEDURE.....5-16

NOTE: When adding to the table of contents, enter the section number, the title, press the tab key and then the page number of the section

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 3 OF 16

1. PURPOSE

This Capability List has been prepared in accordance with the current Code of Federal Regulation (CFR) part 145.215 and the policies of Leach International Corporation and set forth the requirements and policies of this Repair Station, which are to be observed by all repair station employees.

2. APPLICABILITY

This Capability List applies to all repair station employees located at Leach International Corporation which is physically located at 6900 Orangethorpe Avenue in Buena Park, CA 90620. The mailing address is 6900 Orangethorpe Ave, Buena Park CA 90620. The telephone number is 714 739-0770.

3. SCOPE

Capability List includes all the articles on which FJ3D503L Repair Station can perform maintenance, preventive maintenance or alterations. This repair station will not repair or alter any item for which it is not rated, and will not repair or alter any article for which it is rated if it requires technical data, equipment, materials, facilities, or trained personnel that are not available.

4. RECORD RETENTION

Records established to provide evidence of conformity to requirements and of the effective operation of the quality management system shall be controlled in accordance to QAP 2.3 Data Retention/Data Control.

5. REFERENCE DOCUMENTS

<u>Document Number</u>	<u>Document Name</u>
512-0000-000-000	Business Management System Manual
512-0006-000-000	Repair Station & Quality Control Manual
QAP 2.3	Data Retention/Data Control
QAP 9.0	Trade Compliance Program
MRL	Master Records List

6. DEFINITIONS

Term	Definition
Red Flags	<ul style="list-style-type: none"> Any unusual circumstances that indicate a party to transaction is prohibited end-user or Defense Technology / Defense Articles are destined to a prohibited end-use location. Special care should be taken to prevent transactions with entities involved in proliferation of weapons of mass destruction
CFR	<ul style="list-style-type: none"> Code of Federal Regulations

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 4 OF 16

7. ROLES & RESPONSIBILITIES

Role	Responsibilities
Company Employees	<ul style="list-style-type: none"> Maintain full compliance with all applicable laws and regulations that protect and support the national security, foreign policy, and commerce of the United States and other countries in which Company operates

NOTE: Add rows as necessary

8. PROCEDURE

See the Capability List

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 5 OF 16

BALANCED ARMATURE	
9220-4186	9324-10128
9220-4948	9324-10314
9220-8023	9324-10315
9223-8721	9324-10559
9224-3823	9324-10627
9224-4076	9324-7424
9224-4091	9324-8213
9224-4091-CON	9324-8214
9224-4487	9324-8266
9224-4488	9324-8663
9224-5532	9324-8873
9224-5534	9324-9261
9224-8834	9324-9337
9226-3592	9325-10461
9226-4187	9325-8377
9226-4277	9325-8390
9226-4429	9325-8398
9226-5046	9325-8723
9226-6601	9325-8994
9227-10127	9326-4386
9227-10410	9330-4026
9227-10635	9339-10223
9227-4084	9339-10274
9227-4473	9339G-10683
9227-4517	9346-10129
9227-8982	9346-8233
9229-4457	9346-8572
9229-4459	9346-8862
9229-4461	9346-8946
9229-6735	9420-
9235-4842	9524-10214
9237-4845	9524-6506
9237-5567	9524-6507
9274-10291	9524-6508
9274-3642	9524-8208
9274-3643	9524G-10674
9274-6205	9837-10472
9274-6667	9838-10458
9274-6686	9838-10460
9274-7813	9838-10463
9274-8681	9838-10464
9274-8730	9838-10555
9274-9016	9838-10564

POWER DISTRIBUTION ASSEMBLY
CSA-101
PDA-105
PDA-111
PDA-137
PDA-138
PDA-139
PDA-145

GROUND FAULT INTERRUPTER
9130G-10677
9324G-10675
9324G-10676
HDG-X2N-001
HTDG-X7N-001
KCG-X4L-001
KDAG-X4F-001
KDG-X4L-001
HDGE-X3F-001

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 6 OF 16

POWER & CONTROL CONTACTORS			
9123-1Z-C7C4-002	9132-8655	A-A4A-013	C400-9363
9123-8056	9132-8656	A-A4N	C400-9436
9123-8071	9133-8657	A-A4N-103	C400-A1N-223
9123-8072	9133-8678	AH-C6A-020	C400-A2N
9123-8865	9204-6946	AH-C9N-033	C400-B3N
9123-C7C4-002	9205-4584	AH-CXA-016	C400-B3N-001
9123-C7D3-002	9205-7802	AHJS-CXA-040	C600-9374-A
9124-10280	9207	AHS-CXA-034	C600-A11N
9124-10400	9207-10296	AJ-A4N-176	C600-A3A
9124-1Z-C7C4-002	9207-10339	AJ-A7N-210	C600-A3N-001
9124-1Z-C7D3-002	9207-10340	AJ-A8N	C600-A4N
9124-8063	9207-3731	AJ-B4N-180	C600-A9N-001
9124-8073	9207-4399	AJ-B5N	C750-B2F
9124-8075	9207-4521	AJ-B7N-175	C800-9395
9124-8075A	9207-5340	AJ-R1N-220	C800-B10N
9124-9252	9207-7254	AJ-R5N-221	CED-1065
9124-9283	9207-7803	AJ-R7N-222	CED-1066
9124-9290	9207-8053	AJ-T17N-217	C-G1A-010
9124-9318	9207-8339	AJS-A4N-012	CSH-247-1
9124-9417	9207-9238		CSH-267
9124-9426	9207-9274		
9124-9446	9207-9340		
9124-10398	9213-10124		
9124-C7C4-002	9213-3966		
9124-C7D3-002	9840-10558		
9125-2ZC7C4-001	9840-10582		
9130-8463	9901-8768		
9130-8504			
9131-10415			
9131-8388			
9131-8505			
9131-8506			

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 7 OF 16

POWER & CONTROL CONTACTORS				
H-A10N	HC-C3N	L-B3N-014	W-A1N	Z-A1A-052
H-A10N-109	HC-C9N-010	L-B79-013	WC-A3F-018	Z-A2A-080
H-A1A-002	HCD-A1A-011	L-B7N-013	WC-A3F-027	Z-A3YN-079
H-A1F-002	HC-T3A-021	L-B9N-013	WC-A4F-020	Z-A4N
H-A1N	HCTD-A1N-030	LC-A2N-012	WC-A9N-019	Z-A6N
H-A1N-051	HD-A1F-014	LC-B9N-014	WC-A9N-025	Z-A9A-038
H-A1N-059	HD-A3F-011	M600-9336	WE-X2YN-014	Z-A9N-042
H-A2A-002	HD-A9A-021		WE-X9YN-013	Z-B7N-043
H-A2A-021	HD-X9F-011		WL-A10N	Z-B7N-059
H-A2A-043	HD-X9N-025		WL-R9N-016	Z-B7YN
H-A2A-119	HL-A1A-002		W-R1N-033	Z-B9N-062
H-A2A-126	HL-C3N-030		W-R10N-036	ZC-A2N
H-A2F	HLT-A1A			ZC-A2N-020
H-A2F-002	HLT-A1A-002			ZC-A9X-036
H-A2N	H-R4N-143			ZC-B3N
H-A3A-002	H-R10N			ZC-B3N-018
H-A3F	H-R10N-144			ZC-B3N-031
H-A3F-002	HT-A10N			ZC-B4N-021
H-A3N	HT-A4F			ZC-B5F-040
H-A3N-117	HT-A4F-002			ZC-B5N-039
H-A4A-002	HT-A4N			ZC-X9N-044
H-A4A-039	HT-A5A-002			ZCD-B9A-015
H-A4F-002	HT-C7F			ZCD-B9N-012
H-A4N	HT-C7F-072			ZC-B9N-034
H-A4N-120	HT-C7N			ZCD-A1A-047
H-A5A-002	HT-C7N-060			ZCD-A2X-021
H-A5N	HT-C7N-071			ZCD-B9A-012
H-A6N	HT-C7N-073			ZCD-B9A-022
H-A6N-054	HTD-C7N-012			ZCD-B9A-023
H-A6N-157	H-X2A-011			ZC-T5N
H-A9A-004	H-X9A-101			ZD-A5A-045
H-A9A-040	HC-A1N-024			ZD-B4A-011
H-A9A-042				ZD-B4A-017
H-A9A-048				ZD-B9A-016
H-A9N-078				ZE-X9YN-016
H-A9N-093				ZG-A1N
H-C7N				ZG-K7YN-020
H-C9N-011				ZJ-A3N-016
HC-A1A				ZJC-B9N-015
HC-A1A-002				ZJ-T10N-031
HC-A1A-017				Z-R2N-086
HC-A1A-020				Z-R4N-087
HC-A1F-014				Z-T8N-063
HC-A1F-029				Z-X9N-049
HC-A1N				ZL-B7N
HC-A1N-022				

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 8 OF 16

SUBMIN RELAYS				
J-A1A	JC-A1A	J-D1A	JL-A2G-254V	KA-D2F-300L
J-A1A-300M	JC-D1A-003	J-D1A-016	JL- J2A-081	KA-D4F
J-A2A	JC-D1A-102	J-D1A-300M	JL-A2A-039	KA-D4F-033
J-A2B	JC-D1N-103	J-D1N-300M	JL-A2A-042	KA-D4F-036
J-A9A-016	JC-D1N-104	J-D2A-029	JL-A9A-009	KA-D4F-300L
JA-D2F-300L	JC-D2A-003	J-D2A-300M	JL-D1A-023	KA-D4K-300L
JA-D2K-300L	JC-D4A-003	J-D2L-045	JL-D2A-108	KA-D9E-011
JA-D4F-022	JC-D4A-102	J-D2L-138	JL-D2A-116	KA-D9F-005
JA-D4F-034	JC-D4N-103	J-D1A-300M	JL-D2A-163	KA-D9F-010
JA-D4F-300L	JC-D2A-003	J-D1N-300M	JL-D2A-300L	KA-J2K
JA-D4K-300L	JC-D4A-003	J-D2L-149	JL-D2N-300L	KA-J2K-300L
JA-D9E-006	JC-D4A-102	J-D2N	JL-D4A	KA-X4F-007
JA-D9E-009	JC-D4N-103	J-D2N-300M	JL-D4A-300L	KA-X9E-004
JA-D9E-011	JC-D2A-003	J-D4A-017	JL-D4N	K-B4N-300M
JA-D9F-007	JC-D4A-003	J-D4A-019	JL-D4N-300L	
JA-D9F-008	JC-D4N-104	J-D4A-063	JL-D9L-011	
JA-D9F-010	JC-J1A	J-D4A-300M	JL-J2A	
JA-D9L-016	JC-J1N-103	J-D4B-056	JL-J2A-081	
JA-G2K	JC-J2A-102	J-D4L-025	JL-J2B	
JA-J2F-300L	JC-J7N-012	J-D4L-031	JL-J2B-210	
JA-J2K-300L	JC-J9N-009	J-D4L-050	JL-J2B-254V	
JA-W4F-005	JC-X7A-012	J-D4L-115	JL-J2C	
	JCA-D2E	J-D4N	JL-J7A	
	JCL-D4N	J-D4N-059	JL-J7A-017	
		J-D4N-300M	J-W4N-005	
		J-D4N-304M	JL-X9AP-014	
		J-D9B-013		
		J-D9L-006		
		J-G2A		
		J-G2A-019		
		J-G2F-009		
		J-J1N-300M		
		J-J2A-028		
		J-J2A-300M		
		J-J2N-300M		
		J-J7A-300M		
		J-J9A-017		

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 9 OF 16

SUBMIN RELAYS			
KC-A1A	KCL-A1A-014	K-A1A	KDL-D1A-012
KC-A1N	KCL-A1V-020	K-A1A-300M	KDL-D2A-002
KC-A1N-011	KCL-D1A	K-A1N	K-G1A
KC-A4A	KCL-D2A-002	K-A1N-300M	K-G2A
KC-D1A-300L	KCL-D2A-064	K-D1A-300M	K-G2A-014
KC-D1N-300L	KCL-D2A-073	K-D1B-300M	
KC-D2A-003	KCL-D2A-100	K-D1N	
KC-D2A-052	KCL-D2A-110	K-D1N-300M	
KC-D4A-016	KCL-D2A-125	K-D2A-028	
KC-D4L-013	KCL-D2A-254V	K-D2A-109	
KC-D4N-103	KCL-D4A-002	K-D2A-300M	
KCA-E4E	KCL-D4N	K-D2N-300M	
KCA-E4F	KCL-J2A-023	K-D4A-017	
KCA-J2F	KCL-J2A-031	K-D4A-019	
KCA-W9F-008	KCL-J2A-036	K-D4A-025	
KCA-X9F-006	KCL-J2A-047	K-D4B-066	
KC-D2A-300L	KCL-J2A-254V	K-D4L-030	
KC-D2L-059	KCL-X1A-010	K-D4L-036	
KC-D2N-300L	KCL-X1A-011	K-D4L-050	
KC-D4A		K-D4L-113	
KC-D4A-003		K-D4N	
KC-D4A-300L		K-D4N-068	
KC-D4N		K-D4N-300L	
KC-D4N-021		K-D4N-300M	
KC-D4N-033		K-D4N-304M	
KC-D4N-104		K-D4V	
KC-D4N-300L		K-D9L-012	
KC-J2A		K-X1N-008	
KC-J2A-003		KDA-E4E	
KC-J2A-102		KDA-E4F	
KC-J2A-300L		KDA-E4F-002	
KC-J2N-103		KD-A1N	
KC-J2N-300L		KD-A1N-103	
		KD-D1N-103	
		KD-D1N-104	
		KD-D2A-002	
		KD-D2A-018	
		KD-D2N-103	
		KD-D4A	
		KD-D4A-002	
		KD-D4N	
		KD-D4N-103	
		KD-J1A-102	
		KD-J2A-002	
		KD-J2N-103	

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 10 OF 16

SUBMIN RELAYS			
K-J1A	KM-J5N	X-A1A	XL-D4N
K-J2A	KM-U5A	X-A1B	XL-D4N-009
K-J2A-300M	KM-U5AL	X-A1B-300M	XL-J2A
K-J2N-300M	KM-U5N	X-A1A-036	XL-J2A-003
KL-A9A-012	KM-U5NL-011	X-A1A-045	XL-J7A-024
KL-D1B-025	KM-U5NL-012	X-A1N-035	X-X9N-011
KL-D1C	KM-U5NL-014	X-A1N-300M	
KL-D2A-071	KMN-D9N-011	X-A4N-300M	
KL-D2A-085	KUL-X9A-004	X-A9A-014	
KL-D2A-300L	K-W4N-004	X-A9A-020	
KL-D2C	KX-D5N	XA-E9K-011	
KL-D4A-011	KXL-A9A-011	XC-D1A-009	
KL-D4A-037	KXL-A9A-015	XC-J7A	
KL-D4L-025	KXL-X9A-011	XC-J7A-012	
KL-D4L-029	KXL-X9A-012	X-D1A-300M	
KL-D4N	KXL-X9A-022	X-D1N-015	
KL-D4N-300L		X-D1N-018GD	
KL-G2C		X-D1N-019	
KL-X4A-011		X-D1N-300M	
		X-D2N-019	
		X-D2N-300M	
		X-D4A-300M	
		X-D4L-015	
		X-D4N	
		X-D4N-023	
		X-D4N-300M	
		X-E4N-023	
		X-E4N-024	
		X-E4N-300M	
		X-G2N	
		X-J2A	
		X-J2N	
		X-J2N-300M	
		X-J7A-027	
		X-J7A-300M	
		X-J7N-012	
		X-J7N-013	
		XL-A1A	
		XL-A1A-009	
		XL-A9A-015	
		XL-A9A-016	
		XL-D1A-003	
		XL-D1A-017	
		XL-D2A-003	
		XL-D2N	
		XL-D4A	

Leach International Corporation

**CAPABILITY LIST FOR FAA APPROVED
REPAIR STATION NO. FJ3D503L**

DOC NO. **512-0006-001-000**

REV **M**

Release Date:
07/08/2021

SHEET **11** OF **16**

SUBMIN RELAYS	
Y-A1A-300M	Y-D1N-300M
Y-A1N	Y-D2A-019
YA-D4F	Y-D2N-300M
YC-A1N	Y-D2R-300M
YC-A1N-300M	Y-D4N
YC-A4N-300M	Y-D4N-023
YC-D1A-300M	Y-D4N-300M
YC-D1N-300M	Y-E4C-012
YC-D2N-300M	Y-E4N-023
YC-D4A	Y-E4N-024
YC-D4A-300M	Y-E4N-300M
YC-D4N	Y-J2A-016
YC-D4N-300M	Y-J2A-300M
YC-E4N-300M	Y-J2N
YC-J2A-300M	Y-J2N-015
YC-J2N-300M	Y-J2N-300M
YCL-A1A-003	YL-A1A-023
YCL-A1A-016	YL-A1A-026
YCL-A1B-013	YL-D1A-003
YCL-A1B-017	YL-D1A-013
YCL-D1A-003	YL-D4A-003
YCL-D1A-016	YL-D4N
YCL-D1A-254V	YL-J2N
YCL-D1C	
YCL-D4A-003	
YCL-X1A-012	

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 12 OF 16

RELAYS, ELECTRONIC UNITS, TIME DELAY AND TIME DELAY HYBRIDS				
ECU-101		TD-640-30S-1	TD-1700	TD-1982-3001
ECU-103	P111-B253-S001	TD-974	TD-1702-1002	TD-1982-4001
ECU-104	P111-B253-S301	TD-1023	TD-1715-1002	TD-1982-5001
ECU-106	P140-A402-A101	TD-1030	TD-1718-2001	TD-1982-7000
ECU-107-1	P140-A402-A301	TD-1032-B	TD-1721-3500	TD-1982-7500
ECU-108	P150-A153-A031	TD-1040	TD-1738-1002	TD-1982-7501
EP-149	P150-A253-A031	TD-1047	TD-1745	TD-1989-2202
EP-231	P150-A253-A331	TD-1047-10S	TD-1762-1002	TD-1990-3001
EP-361	P150-A702-A332	TD-1047-180S	TD-1781-6002	TD-1996-1202
EP-375	P152-A202-A051	TD-1047-550M	TD-1782-2001	TD-2000-5000
EP-383	P170-A153-A001	TD-1068	TD-1784-1001	TD-2001-1502
EP-393	P170-A202-A001	TD-1069	TD-1796-3002	TD-2004-1002
EP-395	P170-A702-A001	TD-1142	TD-1815-5001	TD-2027-4502
EP-402	P600-A803-E011	TD-1164	TD-1836-5001	TD-2028-2001
EP-410	P600-A803-E013	TD-1192	TD-1854-2500	TD-2040-2501
ECU-111-001	P600-A803-E015	TD-1195	TD-1862-7500	TD-2042-6002
	P700-A154-E002	TD-1197	TD-1862-7500A	TD-635-60S
EP-449-1501	P800-A154-E001	TD-1239	TD-1868-1002	TD-640-10S
EP-449-3001	R101-AXE-5001-FC	TD-1263	TD-1868-2002	TD-640-15S
EP-449-4001	R101-BNJ-2002-BA	TD-1273	TD-1904-5001	TD-640-2S
EP-449-5001	R102-DNE-3003-HB	TD-1324-00	TD-1951-3003	TD-640-300M
EPH-403		TD-1340-00	TD-1955-5000	TD-640-30S
EPH-404		TD-1383-00	TD-1956-2000	TD-640-3S
EPH-423		TD-1412-5000A	TD-1958-5000	TD-640-60S
EPH-345-1		TD-1434-00	TD-1959-6002	TD-770
EPH-438		TD-1684-5001	TD-1971-7500	TD-823
EPH-443		TD-1436-5000W	TD-1972-1251	TD-870-1.4S
EPH-473		TD-1436-5002AW	TD-1975-3003	TD-870-2.1S
EPH-490		TD-1439-01	TD-1982-1000	TD-929
EPH-492-1		TD-1440-00	TD-1982-1002	TD-947
EPH-494		TD-1452-00	TD-1982-1502	TD-948
EPM-112		TD-1468-5000	TD-1982-2001	TD-950
EPM-112-1		TD-1482-7500	TD-1982-2500	TD-975
EPM-112-2		TD-1507-3002	TD-1982-3000	
		TD-1508-3001		
		TD-1542-2002		
		TD-1549-1001		
		TD-1553-1202		
		TD-1626-9002		
		TD-1644-2001		
		TD-1654-3001		

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 13 OF 16

RELAYS, ELECTRONIC UNITS, TIME DELAY AND TIME DELAY HYBRIDS			
TDH-1610-XXXXW	TDH-1994-4502	TDH-8002-XXXX	V110-J-003-AC
TDH-1685-6002	TDH-1999-5001	TDH-8003-XXXX	V110-J-020-AC
TDH-1729-2500	TDH-2006-XXXX	TDH-8050-XXXXP	V110-J-023-AC
TDH-1743-1002	TDH-2012-5001	TDH-8051-XXXXS	V110-J-024-AB
TDH-1798-XXXX	TDH-2021-2001	TDH-8060-XXXXP	V110-J-032-AC
TDH-1852-XXXX	TDH-2029-8001	TDH-8061-XXXXS	V110-K-018-AA
TDH-1853-XXXX	TDH-2030-XXXX	TDH-8070-XXXXP	V110-K-024-AC
TDH-1918-XXXX	TDH-2031-XXXX	TDH-8071-XXXXS	V210-D-090-BC
TDH-1925-XXXX	TDH-6050-XXXX	TDH-8080-XXXXP	V210-K-090-BB
TDH-1960-8001	TDH-6060-XXXX	TDH-8081-XXXXS	V610-BJCC-90
TDH-1961-1002	TDH-6061-XXXX	TDH-8103-1001	V610-HJFF-108
TDH-1962-5001	TDH-6070-XXXX	TDH-8116-XXXX	VS-129
TDH-1964-4001	TDH-6071-XXXX	TDH-8117-5000	VS-215-1
TDH-1965-6001	TDH-6103-XXXX	TDH-8119-XXXX	VS-223-1
TDH-1970-6002	TDH-6108-XXXX	TDH-8120-XXXX	VS-233-1
	TDH-6110-8001	TDH-8124-3403	VS400-2063
	TDH-7050-XXXX	TDH-8127-XXXX	VS-403
	TDH-7051-XXXX	TDH-8140-XXXX	VS-454
	TDH-7060-XXXX	TDH-8150-XXXX	VS-455-1
	TDH-7061-XXXX	TDH-8186-XXXX	VS-456-1
	TDH-7070-XXXX	TDH-8189-XXXX	VS-527
	TDH-7071-XXXX		VS-534
	TDH-7101-XXXX		VS-539
	TDH-7111-0500		VS-568-1
	TDH-7119-7500		VS-576
	TDH-7120-XXXX		VS-584B
	TDH-7122-5001		VS-601
	TDH-7126-0500		VS-621
			VS-629
			VS-630
			VS-633
			VS-635
			VS-636
			VS-643
			VSH-488
			9269-10117
			9269-10139
			9269-3759

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 14 OF 16

LEACH INTERNATIONAL EUROPE (LIE)					
PANELS	MECHANICAL/ELECTRONIC ASSEMBLY		OVERHEAD PANELS	PC BOARDS	
	90020	FE940		FE892	FE1248-5
90020-2	FE1137	FE892-01	FE1248-5A	00 2320 00	FE1066
90050-3	FE1524-03	FE892-02	FE1248-6	00 2352 00	FE1089
90050-4	FE1524-04	FE897	FE1248-6A	00 2353 00	FE1089-1
90200-1	FE1525-03	FE1608L-516	FE1248-7	00 2368 00	FE1121
90200-2	FE1525-04	FE1608R-520	FE1248-7A	00 2369 02	FE1141
90300-4	FE1549R-01		FE1331-5	00 2569 00	FE1145
90310	FE1549R-02		FE1331-5A	00 2569 01	FE1210
90350-1	FE1561		FE1385S3-5	00 2570 00	FE1243
92417	FE1561-01		FE1385S3-5A	00 2570 01	FE1243-1
92418	FE1561-02		FE1385S3-5B	FE422-01	FE1243-2
	FE1561-03		FE1385S3-5AB	FE457	FE1263
00 2265 00	FE1607-512		FE1385S3-6	FE460	FE1278
00 2358 01	FE1609-520		FE1385S3-6A	FE463	FE1280
00 3225 00	FE1610L-524		FE1385S3-6B	FE466	FE1482-3
FE1144	FE1610R-518		FE1385S3-6AB	FE549	FE1509-01
FE1328	FE1611-520		FE1385S3-8	FE695	FE1509-02
FE1401	FE1611-522		FE1385S3-8A	FE713	FE1509-03
FE1415	FE1612-514		FE1385S3-8B	FE714	FE1509-06
FE1422-1	FE1489		FE1385S3-8AB	FE799	FE1510
FE1526-04	FE1549L		FE1533	FE800	FE1548-01
FE1526-05	FE1549L-01		FE1533-A	FE854	FE1663
FE1550-02	FE1549R			FE886	FE1718
FE1551-02	FE1549R-03			FE888	FE1718-01
FE1574-05	FE1526-03			FE953	FE1851-1
FE925-1				FE964	FE1851-2
FE950-1				FE1002	00 4849 81
				FE1002-1	FE422
				FE1027	FE424
				FE1038	FE1056

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 15 OF 16

SUB-ASSEMBLIES FOR OVERHEAD PANELS (LIE)			
00 3516 00	00 3742 81	00 3982 02	00 4130 46
00 3714 00	00 3742 41	00 6185 00	00 4130 47
00 3736 00	00 3742 42	00 4130 00	00 4130 48
00 3737 00	00 3742 43	00 4130 01	00 4130 49
00 6186 00	00 3742 44	00 4130 02	00 4130 50
00 6187 00	00 3742 45	00 4130 03	00 4130 51
00 6188 00	00 3742 46	00 4130 04	00 4130 52
00 3742 00	00 3742 48	00 4130 05	00 4130 53
00 3742 01	00 3742 49	00 4130 06	00 4130 54
00 3742 02	00 3742 50	00 4130 07	00 4130 55
00 3742 03	00 3742 51	00 4130 08	00 4130 56
00 3742 04	00 3742 52	00 4130 09	00 4130 57
00 3742 05	00 3742 53	00 4130 10	00 4130 58
00 3742 06	00 3742 54	00 4130 11	00 4130 59
00 3742 07	00 3742 56	00 4130 12	00 4130 60
00 3742 08	00 3742 57	00 4130 13	00 4130 61
00 3742 09	00 3742 58	00 4130 14	00 4130 62
00 3742 10	00 3742 60	00 4130 15	00 4130 63
00 3742 11	00 3742 61	00 4130 16	00 4130 64
00 3742 12	00 3742 62	00 4130 17	00 4130 65
00 3742 13	00 3742 63	00 4130 18	00 4130 66
00 3742 14	00 3742 64	00 4130 19	00 4130 67
00 3742 15	00 3742 65	00 4130 20	00 4130 68
00 3742 16	00 3742 66	00 4130 21	00 4130 69
00 3742 17	00 3742 67	00 4130 22	00 4130 70
00 3742 18	00 3742 68	00 4130 23	00 4130 71
00 3742 19	00 3742 69	00 4130 24	00 4849 81
00 3742 20	00 3742 70	00 4130 25	
00 3742 21	00 3742 71	00 4130 26	
00 3742 22	00 3742 72	00 4130 27	
00 3742 23	00 3742 73	00 4130 28	
00 3742 24	00 3742 74	00 4130 29	
00 3742 25	00 3742 75	00 4130 30	
00 3742 26	00 3742 76	00 4130 31	
00 3742 27	00 3742 77	00 4130 32	
00 3742 28	00 3742 78	00 4130 33	
00 3742 29	00 3742 79	00 4130 34	
00 3742 30	00 3742 80	00 4130 35	
00 3742 31	00 3742 82	00 4130 36	
00 3742 32	00 3742 83	00 4130 37	
00 3742 33	00 3742 84	00 4130 38	
00 3742 34	00 3742 86	00 4130 39	
00 3742 35	00 3791 00	00 4130 40	
00 3742 36	00 3791 01	00 4130 41	
00 3742 37	00 3791 02	00 4130 42	
00 3742 38	00 3792 00	00 4130 43	
00 3742 39	00 3982 00	00 4130 44	
00 3742 40	00 3982 01	00 4130 45	

Leach International Corporation	
CAPABILITY LIST FOR FAA APPROVED REPAIR STATION NO. FJ3D503L	
DOC NO. 512-0006-001-000	REV M
Release Date: 07/08/2021	SHEET 16 OF 16